

FIG. 1




FIG.2A




FIG.2B




FIG.3A

Di0

	A	B	C	D
a	52	152	52	52
b	52	152	52	52
c	48	148	48	48
d	48	148	48	48

FIG.3B

Da0

	La=100 Lb=100			
a	0	1	0	0
b	0	1	0	0
c	0	1	0	0
d	0	1	0	0

FIG.3C

Db0

	A	B	C	D
a	50	150	50	50
b	50	150	50	50
c	50	150	50	50
d	50	150	50	50

FIG.3G

Dv1

	A	B	C	D
a	0	0	0	0
b	0	0	0	0
c	0	0	0	0
d	0	0	0	0

FIG.3D

Di1

	A	B	C	D
a	52	152	52	52
b	52	152	52	52
c	48	148	48	48
d	48	148	48	48

FIG.3E

Da1

	La=100 Lb=100			
a	0	1	0	0
b	0	1	0	0
c	0	1	0	0
d	0	1	0	0

FIG.3F

Db1

	A	B	C	D
a	50	150	50	50
b	50	150	50	50
c	50	150	50	50
d	50	150	50	50

FIG.3H

Dq0

	A	B	C	D
a	52	152	52	52
b	52	152	52	52
c	48	148	48	48
d	48	148	48	48

FIG.4




FIG. 5A




FIG. 5B




FIG. 5C




FIG. 6A




FIG. 6B




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG.12




FIG.13




FIG. 14




FIG. 15




FIG.16




FIG.17




FIG.18




FIG. 19




FIG. 20




FIG. 21A




FIG.21B

